




XF - MH 0 4 5 X 7 5

0 . 4 5
Ü 2 4 . 4 mm
Ü 1 1 mm
7 5 mm ± 3 %
3 . 2 mm
F 6
8 . 8 ÷ m
> 0 . 3 @ 1 5 0 l p / mm
< 0 . 0 7 9 %

2 / 3 ' 8 . 4 5 8 7 8 0 1 5 . 7 mm
1 / 1 . 8 ' 7 . 2 1 5 . 3 1 1 . 8 mm
1 / 2 ' 6 . 4 1 4 . 2 1 0 . 7 mm
1 / 3 ' 4 . 8 1 3 . 6 8 . 0 mm

E		E	D		
X . X	± 0 . 2	± 3 0 m i n	XF - MH 0 4 5 X 7 5 -		
X . X X	± 0 . 0 2				
X . X X X	± 0 . 0 0 5	' A 3			
		/		D	ap
				2 : 1	
1					
2			"		